

Abyei Referral Hospital Existing Structure Pictures:

A. Front Elevations:



Right side



Left Side.

B. Side Elevations-East side:



Left side



Right side



Back side

C. Side Elevations-West side:



D. Back Elevations:



Right side



Left side



Back

E. Existing Roof steels members to be removed:(Substandard steel work)







F. Guard House to be completed:



G. Septic Tanks to be completed:



Septic tank number 01-Bottom and side steel in place.



Septic tank number 02-Top cover needed.